

NOTICE TO MARINERS

No 11(T) of 2018

Port of Southampton – Southampton Water – Bald Head Buoy – Light Extinguished and Topmark Missing

NOTICE IS HEREBY GIVEN that the light on the Bald Head navigation buoy in Southampton Water (50° 49.801'N, 01° 18.065'W) is currently extinguished and the Topmark is missing.

Vessels are requested to proceed with caution when navigation in the vicinity of the North Thorn buoy. Ahead of their passage, mariners may also request shipping information from Southampton VTS on VHF Channel 12.

This notice will be self-cancelling upon rectification of the defect.

**Ocean Gate
Atlantic Way
Southampton, SO14 3QN**

**Captain P J A Buckley
Harbour Master**

27th March 2018

**Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing
Organisations should ensure that the contents of this Notice are made known to
the masters or persons in charge of their vessels or craft.**